

Comments on
B&B Superfund Site Activity Report

Prepared by
G. Fred Lee, PhD, Technical Assistance Grant Advisor to CBA
G. Fred Lee & Associates
El Macero, CA

July 17, 2013

URS, the contractor for DTSC for the B&B Superfund site cap inspection/repair, issued the following report
http://www.envirostor.dtsc.ca.gov/regulators/deliverable_documents/4272520303/10-T1114%20Status%20Summary%20Brown%20and%20Bryant%20Site%20%282Q13%29.pdf

*Project Status Summary for April 1 through June 30, 2013
Brown and Bryant Site, Arvin, California
Agreement No. 10-T1114 A-2
W.O. No. 1-114-1.0-100025
Prepared: July 15, 2013*

That report presents a DTSC Envirostor Report that lists in the “summary of work completed”:

“TASK 5 – Implement Cap Repair Work Plan, Monitor, Inspection, and Maintenance of OU 1 Remedial Systems
 Performed job walk is scheduled for April 29, 2013.
 Performed repairs on Tuesday June 25 through Thursday June 27, 2013 performing weed eating, spraying pre-emergent and completing the crack repairs. The animal burrows and small fence fixes were completed on Wednesday July 3, 2013.

No information was presented in the URS report on the conditions found at the time of inspection, the location or extent of problems found, or how the actions taken addressed the deficiencies found.

G. Fred Lee